

FIG. 1
(PRIOR ART)




FIG. 2 — SERVO SAMPLE WEDGES 107
(PRIOR ART)




FIG. 3
(PRIOR ART)




FIG. 4A




FIG. 4B





FIG. 4C






FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10A




FIG. 10B




FIG. 10C




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16